

IT 认证电子书



质 量 更 高 服 务 更 好

半年免费升级服务

<http://www.itrenzheng.com>

Exam : CSSBB

**Title : Six Sigma Black Belt
Certification - CSSBB**

Version : DEMO

1. Control Charts were developed by Dr. Shewhart to track data over time. To detect Special Cause variation the Control Charts use which of these?

- A. Data shift analysis
- B. Outlier analysis methods
- C. Center Line and Control Limits
- D. None of the above

Answer: C

2. A _____ is used primarily to track the stability of the average value of a metric of interest.

- A. NP Chart
- B. Xbar-R Chart
- C. I-MR Chart
- D. C Chart

Answer: B

3. Common and _____ Cause Variation are the focus of Statistical Process Control.

- A. Uncommon
- B. Ordinary
- C. Special
- D. Selective

Answer: C

4. In a good Measurement System the most variation will be with part-to-part measurements.

What should you do if the majority of variation is associated with the Gage R&R assuming the gage is technically capable?

- A. Focus on fixing the Repeatability and Reproducibility of the measurement device
- B. Purchase a new machine
- C. Focus on trimming the Part-to-Part variation
- D. Run another MSA test with the machine

Answer: A

5. Which statement(s) are incorrect about Fractional Factorial Designs?

- A. A Half Fractional Design for 5 factors has the same number of experimental runs as a Full Factorial Design for 4 factors assuming no repeats or replicates or Center Points
- B. Quarter Fractional experiments can exist for those with 4 factors
- C. Resolution V design is desired while controlling costs of experimentation
- D. Half Fractional experiments do not exist for those designs with only 2 factors

Answer: C