认证电子书



质 量 更 高 服 务 更 好

半年免费升级服务

http://www.itrenzheng.com

Exam : HP0-513

Title : AlphaServer System

Maintenance (formerIt

#330-610)

Version: DEMO

| 1. Where can you check an AlphaServer's serial number for warranty status? |
|---|
| A. SRL |
| B. CSN |
| C. QRL |
| D. OMNI |
| Answer: B |
| |
| 2. Which type of PCI bus slot is available on an AlphaServer DS10L? |
| A. 16-bit |
| B. 32-bit |
| C. 64-bit |
| D. 128-bit |
| Answer: C |
| |
| 3. Which AlphaServer does NOT have an interlock switch? |
| A. DS10 |
| B. DS20 |
| C. DS20E |
| D. ES40 |
| Answer: A |
| |
| 4. When installing a new Alpha system, which command would you use with the Loadable Firmware Utility |
| (LFU) to verify option firmware revision level? |
| A. check |
| B. update |
| C. show revision |
| D. list |
| Answer: D |
| |

5. On an AlphaServer ES40, what information is obtained from the "show fru -e" command?

| A. FRU firmware version |
|--|
| B. extended fru status |
| C. FRU environmental variables |
| D. FRU with errors |
| Answer: D |
| |
| 6. Alpha console firmware updates can be performed using all of the following, EXCEPT |
| A. CD-ROM |
| B. floppy disk |
| C. the network |
| D. replacing the chip |
| Answer: D |
| |
| 7. Which FRUs are defined as hot-pluggable on the AlphaServer DS20? |
| A. individual fans |
| B. hard drives |
| C. PCI options |
| D. power supplies |
| Answer: B |
| |
| 8. What is ONE of the configuration rules when installing DIMMs on an AlphaServer ES40? |
| A. One DIMM in each memory motherboard. |
| B. Fill odd memory sets first. |
| C. Fill even memory sets first. |
| D. Fill sets in numerical order. |
| Answer: D |
| |
| 9. When an AlphaServer DS20 has correctable memory errors, what action does the system take? |
| A. crashes and re-boots |
| B. halts to console |

| C. resets |
|---|
| D. continues running |
| Answer: D |
| |
| 10. Which file contains the Tru64 UNIX startup and error information? |
| A. event.log |
| B. messages |
| C. sysfile |
| D. errorlog.sys |
| Answer: B |
| |
| 11. Which component is hot-swappable on the ES40? |
| A. fan |
| B. CPU |
| C. memory |
| D. PCI option |
| Answer: A |
| |
| 12. What must be considered when installing an AlphaServer DS20? |
| A. Do not install the system under a desk. |
| B. Do not install the rear of the system against a wall. |
| C. Install the system only in a computer room. |
| D. The system must be installed in a rack. |
| Answer: B |
| |
| 13. AlphaServer firmware upgrades are performed for what purpose? Select TWO. |
| A. Add new hardware support. |
| B. Recognize new memory. |
| C. Remove old options. |
| D. Perform firmware bug fixes. |

| E. Rebuild kernel. |
|--|
| Answer: AD |
| |
| 14. Which command option overrides any setting of the boot_osflags environment variable? |
| A flags |
| B osflags |
| C boot |
| D vars |
| Answer: A |
| |
| 15. Which background process must be running for Compaq Analyze to function? |
| A. desta_exec |
| B. analyze_exec |
| C. webes_exec |
| D. ca_exec |
| Answer: A |
| |
| |
| 16. If you remove a PCI option card and do not replace it, what is the necessary action you must take? |
| 16. If you remove a PCI option card and do not replace it, what is the necessary action you must take?A. Replace the PCI option cover. |
| |
| A. Replace the PCI option cover. |
| A. Replace the PCI option cover. B. No action necessary. |
| A. Replace the PCI option cover. B. No action necessary. C. Install a filler PCI airflow card. |
| A. Replace the PCI option cover.B. No action necessary.C. Install a filler PCI airflow card.D. Terminate the PCI slot. |
| A. Replace the PCI option cover.B. No action necessary.C. Install a filler PCI airflow card.D. Terminate the PCI slot. |
| A. Replace the PCI option cover. B. No action necessary. C. Install a filler PCI airflow card. D. Terminate the PCI slot. Answer: A |
| A. Replace the PCI option cover. B. No action necessary. C. Install a filler PCI airflow card. D. Terminate the PCI slot. Answer: A 17. Which SRM console environment variable identifies the SCSI controller ID? |
| A. Replace the PCI option cover. B. No action necessary. C. Install a filler PCI airflow card. D. Terminate the PCI slot. Answer: A 17. Which SRM console environment variable identifies the SCSI controller ID? A. pk*_host_id |
| A. Replace the PCI option cover. B. No action necessary. C. Install a filler PCI airflow card. D. Terminate the PCI slot. Answer: A 17. Which SRM console environment variable identifies the SCSI controller ID? A. pk*_host_id B. SCSI_ID |

| 18. Which URL invokes Compaq Analyze on the local node? |
|--|
| A. http://localhost :7902 |
| B. http://localhost :80 |
| C. http://localhost :1705 |
| D. http://localhost :2981 |
| Answer: A |
| |
| 19. Two additional CPUs have been added to ES40. After the addition of these CPUs, the system does |
| not initialize properly. What could resolve this problem? |
| A. More cache needs to be added. |
| B. A second power supply is needed. |
| C. A second cabinet fan needs to be added. |
| D. Add a voltage regulator for each CPU. |
| Answer: B |
| |
| 20. Which SRM command is used to verify the proper functioning of the system components during |
| system installation? |
| A. test |
| B. diag |
| C. boot |
| D. sysex |
| Answer: A |
| |
| |